#### **UNCLASSIFIED**

# AD NUMBER AD808382 LIMITATION CHANGES TO: Approved for public release; distribution is unlimited. FROM: Distribution authorized to U.S. Gov't. agencies and their contractors; Administrative/Operational Use; AUG 1966. Other requests shall be referred to Air Force Flight Dynamics Lab., Wright-Patterson AFB, OH 45433. AUTHORITY AFFDL ltr 29 Dec 1971

808385

# AIRCRAFT GROUND-PLOTATION INVESTIGATION PART VIII DATA REPORT ON TEST SECTION 7

W. BRABSTON and W. HILL, JR.
U. S. ARMY ENGINEER WATERWAYS EXPERIMENT STATION

TECHNICAL REPORT AFFOLTR-00-48, PART VIII
AUG-OF 1906

This document is subject to special expect controls and each trusmittal to feroign governments or fureign notionals may be made only will geter approval of the Air Force Flight Demonies Lob-restory (FDFS), Weight-Felterson Air Force Bure, Ohio 45AM.

AR PORCE PLEGRY DYNAMICS LABORATORY RESEARCH AND TECHNOLOGY DIVISION ARE PURCE STREETS COMMAND WEIGHT-PATTER ON AIR PURCE BASE, OHIO

# Best Available Copy

#### NOTICES

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

Copies of this report should not be returned to the Research and Technology Division unless return is required by security considerations, contractual obligations, or notice on a specific document.

259 - Outobie 1508 6-627

# AIRCRAFT GROUND-FLOTATION INVESTIGATION PART VIII DATA REPORT ON TEST SECTION 7

W. BRABSTON and W. HILL, JR.
U. S. ARMY ENGINEER WATERWAYS EXPERIMENT STATION

This document is subject to special expect controls and each transmittal to foreign governments or foreign nationals may be made only with prior approval of the Air Force Flight Dynamics Laboratory (FDFM). Wright-Patterson Air Force Base, Ohio 48423.

#### FORD

The investigation described herein constitutes one phase of studies conducted during 1964 and 1965 at the U.S. Army Engineer Waterways Experiment Station (WES) under U.S. Air Force Project No. 410-A, MIPR No. AS-4-177, "Development of Landing Gear Design Criteria for the CX-HIS Aircraft." (The CX-HIS is now designated C-5A.) This program was sponsored and directed by the Landing Gear Group, Air Force Flight Dynamics Laboratory, Research and Technology Division, Mr. R. J. Parker, Project Engineer.

These tests were conducted by personnel of the WES Flexible Pavement Branch, Soils Division, under the general supervision of Messrs. W. J. Turnbull, A. A. Maxwell, and R. G. Ahlvin, and the direct supervision of Mr. D. N. Brown. Other personnel actively engaged in this study were Messrs. C. D. Burns, D. M. Lada, W. N. Brabston, A. H. Rutledge, H. H. Ulery, Jr., A. J. Smith, Jr., and W. J. Hill, Jr. This report was prepared by Messrs. Brabston and Hill.

Directors or WES during the conduct of this investigation and preparation of this report were Col. Alex G. Sutton, Jr., CE, and Col. John R. Oswalt, Jr., CE. Technical Director was Mr. J. B. Tiffany.

Publication of this technical documentary report does not constitute Air Force approval of the report's findings or conclusions. It is published only for the exchange and stimulation of ideas.

KENNERLY H. DIGGES

Chief, Mechanical Branch Vehicle Equipment Division

AF Flight Dynamics Laboratory

the straight given when the course of the course of the straight of the print of the straight of the straight

PRESENCE AND PROPER PARK. Drille at all all

#### ABSTRACT

This data report describes work undertaken as part of an overall program to develop ground-flotation criteria for the C-5A aircraft. A test section was constructed to a width adequate for four unsurfaced test lanes having approximately the same subgrade CBR values. Single-wheel traffic was applied to each lane using one of the following tire size and test load combinations: (a) a 56x16, 32-ply aircraft tire with 25,000-lb load; (b) a 25.00-28, 30-ply aircraft tire with 25,000-lb load; (c) a 17.00-16, 12-ply aircraft tire with 25,000-lb load; and (d) a 34x9.9, 14-ply aircraft tire with 19,000-lb load. Tire inflation pressure was 100 psi for all tires.

The information reported herein includes layout of the test lanes, characteristics and print dimensions of the load assembly tires, and data collected on soil strengths, surface deformations and deflections, and drawbar pull. The traffic-coverage level is given at which each test lane was considered failed.

#### CONTENTS

				Page
SECTION I: INTRO	DUCTION			1
SECTION II: DESC	CRIPTION OF TEST SEC	TION AND LOAD VEHIC	IIE	2
	of Test Section			2
	PLICATION OF TRAFFIC TA COLLECTED			2
	of Traffic teria and Data Coll			3
SECTION IV: BEHA	VIOR OF LANES UNDER	TRAFFIC AND TEST I	RESULTE	5
Lane 13				5
				5
				7
SECTION V: PRINC	CIPAL FINDINGS			9

#### ILLUSTRATIONS AND TABLES

		Pa	age
Figure			
1.	Load vehicle used on lanes 13 and 14		13
2.	Load vehicle used on lanes 15 and 16		13
3 -	Lane 13 prior to traffic		14
4.	Lane 13; general view showing transverse straightedge measurement at 70 coverages (failure)		14
5.	Lane 14 prior to traffic		15
6.	Lane 14; general view showing transverse straightedge measurement at 200 coverages (failure)		15
	Lane 15 prior to traffic		10
8.	Lane 15; general view showing transverse straightedge measurement at 100 coverages (failure)		16
	Lane 16 prior to traffic		17
	General view of lane 16 after 32 coverages (failure)		17
	Layout of Test Section 7 and summary of test results		18
	Tire-print dimensions and tire characteristics		7.9
4	Traffic distribution patterns		20
14.	Average cross-sectional deformations		21
and the same of th	Permanent profile deformations		22
16.	Average total soil deflections		23
Table			
1.	Summary of Traffic Data, Test Section 7 Summary of CBR, Density, and Water Content Data,		11
£ •	Test Section 7		12

#### SUMMARY

Tests on Section 7 are one phase of a comprehensive research program to develop ground-flotation criteria for heavy cargo-type aircraft. Test Section 7 consisted of four similar traffic lanes (lanes 13, 14, 15, and 16), all of which were unsurfaced and constructed to approximately the same CBR value (figure 11). The four test lanes were subjected to traffic by single-wheel tracking assemblies using a different tire size and test load combination on each lane. The following combinations of tire size and test load were used on lanes 13, 14, 15, and 16, respectively: (a) a 56x16, 32-ply aircraft tire with 25,000-lb load; (b) a 25.00-28, 30-ply aircraft tire with 25,000-lb load; (c) a 17.00-16, 12-ply aircraft tire with 25,000-lb load; and (d) a 34x9.9, 14-ply aircraft tire with 19,000-lb load. Inflation pressure for all tires was 100 psi.

The test lanes were trafficked to failure in accordance with the criteria designated in Part I of this report. Data were recorded throughout testing to give a behavior history of each lane. Using the test criteria mentioned above, it was possible to directly compare the effects of trafficking with the four assemblies. Basic performance data are summarized in the following paragraphs.

#### Lane 13

The lane was considered failed due to rutting at 70 coverages. The rated CBR of the lane was 9.2.

#### Lane 14

The lane was considered failed due to excessive transverse differential deformations at 200 coverages. The rated CBR of the lane was 7.8.

#### Lane 15

The lane was considered failed due to excessive transverse

differential deformations at 100 coverages. The rated CBR of the lane was 7.8.

#### Lane 16

The lane was considered failed due to rutting at 32 coverages. The rated CBR of the lane was 8.4.

#### AIRCRAFT GROUND-FIOTATION INVESTIGATION

#### PART VIII DATA REPORT ON TEST SECTION 7

#### SECTION I: INTRODUCTION

The investigation reported herein is one phase of a comprehensive research program being conducted at the U. S. Army Engineer Waterways Experiment Station (WES), Vicksburg, Miss., as part of U. S. Air Force Project No. 410-A, MIPR No. AS-4-177 to develop ground-flotation criteria for the C-5A, a heavy cargo-type aircraft. Specifically, the tests reported herein were conducted to determine the effect of wheel size of single-wheel landing-gear assemblies on unsurfaced soils under similar conditions of loading.

Prosecution of this investigation consisted of constructing four similar test lanes and subjecting them to traffic of four single-wheel tracking assemblies, each consisting of a different size aircraft tire. Three of the lanes were trafficked with 25,000-lb loads and one was trafficked with a 19,000-lb load. Tire inflation pressure was 100 psi for all assemblies.

This report presents a description of the test section and wheel assemblies, and gives results of traffic. Equipment used, types of data and method of recording them, and general test criteria are explained and illustrated in Part I of this report.

to teach and it is ferror and an extension property to the law in teach of the law in the

AND THE PROPERTY OF THE PARTY O

The complete profession of the control of the contr

#### SECTION II: DESCRIPTION OF TEST SECTION AND LOAD VEHICLE

#### Description of Test Section

Test Section 7 was constructed within a roofed area in order to allow control of the subgrade CBR (California Bearing Ratio) in the test lanes. Section 7 was located on the same site as Test Sections 3 and 5. The construction of Test Section 3 is described in Part IV of this report. The underlying subgrade was undisturbed by the two prior tests on the site so that in construction of Section 7 only the upper 18 in. of soil was excavated. The excavated area was backfilled to the original grade level in four compacted lifts with a heavy clay soil (buckshot; classified as CH according to the Unified Soil Classification System, MIL-STD-619). The fill material used was a local clay with a plastic limit of 27, liquid limit of 58, and plasticity index of 31. Gradation and classification data for the subgrade material are given in Part I.

Four traffic lanes were constructed in the test section, having approximately the same subgrade CBR values. All lanes were unsurfaced.

#### Load Vehicle

The load vehicle used for trafficking lanes 13 and 14 is shown in figure 1. Load cart construction, details of linkage between the load compartment and prime mover, and method of applying load are explained in Part I. For both lanes, a single-wheel assembly was used with a load of 25,000 1b and tire inflation pressure of 100 psi. The assemblies consisted of a 56x16, 32-ply aircraft tire and a 25.00-28, 30-ply aircraft tire for lanes 13 and 14, respectively.

For trafficking lanes 15 and 16, the load vehicle shown in figure 2 was used with loads of 25,000 lb and 19,000 lb, respectively. For both lanes, a single-wheel assembly was used with tire inflation pressure of 100 psi. The assemblies consisted of a 17.00-16, 12-ply aircraft tire and a 34x9.9, 14-ply aircraft tire for lanes 15 and 16, respectively.

Tire-print data and pertinent tire characteristics for the wheel assemblies used on Section 7 are given in figure 12.

SECTION III: APPLICATION OF TRAFFIC, FAILURE CRITERIA, AND DATA COLLECTED

#### Application of Traffic

Traffic was applied to the test lanes in a nonuniform pattern with intensity of traffic being varied within each lane to produce three zones of approximately 100, 80, and 20 percent traffic coverage. Traffic so distributed within a traffic lane simulates as nearly as possible the bell-shaped traffic distribution curve which results from the wander of aircraft from the lane center line. The coverage levels referred to in the tables and text herein are the total number of coverages applied to the 100 percent coverage zone. The corresponding number of coverages applied to the outer traffic zones is proportional to the percentage factor for the respective zones, as shown in figure 13.

#### Failure Criteria and Data Collected

Failure criteria used in this investigation and descriptive terms used in presentation and discussion of data are presented in Part I. A general outline of types of data collected is given in the following paragraphs. Details on apparatus and procedure for obtaining specific measurements are given in Part I.

#### CBR, water content, and dry density

CBR, water content, and dry density of the subgrade were measured for each test lane prior to application of traffic, at intermediate coverage levels, and at failure. After traific was concluded on a lane, a measure of subgrade strength termed "rated CBR" was determined. Rated CBR is generally the average CBR value obtained from all the determinations made in the top 12 in. of soil during the test life of a lane. In certain instances extreme or irregular values may be ignored if the analyst decides that they are not properly representative.

#### Surface roughness, or differential deformation

Surface roughness, or differential deformation, measurements were made using a 10-ft straightedge at various traffic-coverage levels on all lanes. Rut depths were also measured on test lanes.

#### Deformations

Deformations, defined as permuent cumulative surface changes in cross section or profile of a lane, were charted by means of level readings at pertinent traffic-coverage levels.

#### Deflection

Deflection of the test surface under an individual static load of the tracking assembly was measured at various traffic-coverage levels on each lane. Level readings on the lane surface on each side of the load wheel and on a pin and cap device directly beneath the load wheel provided deflection data. Both total (for a single loading) and elastic (recoverable) deflections were measured.

### Rolling resistance

Rolling resistance, or drawbar pull, measurements were performed with the load vehicle over each test lane at designated coverage levels. Three types of drawbar measurements were taken: (a) maximum force required to overcome static inertia and commence forward movement of the load cart, termed "initial DBP"; (b) average force required to maintain a constant speed once the load vehicle is in motion, termed "rolling DBP"; and (c) maximum force obtained during the constant speed run, termed "peak DBP."

with the property of the second secon The fact and professional services in the contract of the cont

distant of the particular to the particular to the last the particular

ribbles that the females is to be start a fight with a start

#### SECTION IV: BEHAVIOR OF LANES UNDER TRAFFIC AND TEST RESULTS

#### Lane 13

#### Behavior of lane under traffic

Figure 3 shows lane 13 prior to traffic. The surface was moderately rutted at 20 coverages with rut depths averaging 1.5 in. Traffic was continued until the lane was considered failed due to rutting at 70 coverages (figure 4). The rated CBR of the lane was 9.2.

#### Test results

Results of trafficking lane 13 are summarized in table 1. Soil test data are given in table 2. Table 1 contains drawbar pull values for the load vehicle operated over an asphalt-paved strip for comparison with drawbar values recorded on the test lane. The following information was obtained from traffic tests on lane 13.

- a. Roughness. Table 1 shows the progressive development of differential deformations and rut depths with traffic. At failure, both transverse and diagonal differential deformations averaged 3.69 in. Longitudinal deformations were relatively small, averaging 0.69 in. Rut depths averaged 3.31 in. at failure.
- b. Deformation. Figure 14 shows the average cross-section deformations at 20 and 70 coverages. Center-line profiles at 20 and 70 coverages are plotted in figure 15.
- c. Deflection. Average total soil deflections measured at 0, 20, and 70 coverages are plotted in figure 16. Total soil deflection at 70 coverages was about twice as great as in prior measurements. Elastic soil deflections increased similarly, as indicated in table 1.
- d. Rolling resistance. Drawbar pull values measured at several coverage levels are shown in table 1. Drawbar values were small at all levels and increased only slightly with traffic. Minimum initial and peak drawbar values occurred at 20 coverages.

#### Lane 14

#### Behavior of lane under traffic

Figure 5 shows lane 14 prior to traffic. The test surface held up well under testing and traffic was continued to 200 coverages at which time the lane was considered failed due to excessive transverse differential

deformations (figure 6). The rated CBR of the lane was 7.8.

#### Test results

Results of trafficking lane 14 are summarized in table 1. Soil test data are given in table 2. The following information was obtained from traffic tests on lane 14.

- a. Roughness. Table 1 shows the differential deformations and rut depths measured at intervals during testing. Transverse and diagonal differential deformations exceeded in magnitude other deformation measurements and averaged 3.50 and 3.56 in., respectively, at failure. Due to the uniform subsidence in the lane cross section, rut depths were not great and averaged only 1.16 in. at failure.
- b. Deformation. Average cross-section deformations at 20 and 200 coverages are plotted in figure 14. Center-line profiles are plotted in figure 15. Both figures illustrate the extensive subsidence that developed along the lane center line.
- c. Deflection. Average total soil deflections measured at 0, 20, and 200 coverages are plotted in figure 16. Greatest total deflections occurred at 200 coverages. Elastic soil deflections, shown in table 1, registered no significant change with traffic.
- d. Rolling resistance. Drawbar pull values measured at 0, 20, and 200 coverages are shown in table 1. All drawbar values decreased slightly between 20 and 200 coverages.

## <u>Lane 15</u>

#### Behavior of lane under traffic

Figure 7 shows lane 15 prior to traffic. The lane was considered failed at 100 coverages primarily due to excessive transverse differential deformations (figure 8). The rated CBR of the lane was 7.3.

#### Test results

Results of trafficking lane 15 are summarized in table 1. Soil test data are given in table 2. The following information was obtained from traffic tests on lane 15.

a. Roughness. Table 1 shows differential deformations and rut depths measured at 20 and 100 coverages. Transverse and diagonal differential deformations were largest and averaged 3.62 and

3.83 in., respectively, at failure. Rutting was less severe, averaging 2.15 in. at failure.

- b. Deformation. Average cross-section deformations are plotted in figure 14 for 20 and 100 coverages. The same coverage levels are represented in the center-line plot in figure 15.
- c. Deflection. Average total soil deflections measured at 0, 20, and 100 coverages are plotted in figure 16. Only small increases in total deflection resulted from traffic. Elastic soil deflections, shown in table 1, increased slightly.
- d. Rolling resistance. Drawbar pull values, shown in table 1, increased progressively during testing with maximum values occurring at 100 coverages.

#### Lane 16

#### Behavior of lane under traffic

Figure 9 shows lane 16 prior to traffic. Severe ruts developed early in testing with high ridges forming between the ruts. It became impossible beyond 14 coverages to track the ridged strips, as the load wheel continually slipped sideways into an adjacent rut. The relative heights of the ridges increased with continued trafficking due to soil upheaval from the rutted areas. To obtain more representative roughness data, the influence of the ridge areas was de-emphasized by cutting access notches across the ridges so that for differential deformation measurements the ends of the 10-ft straightedge rested on the undisturbed surfaces outside the tracking lane. Figure 10 shows the lane after it was judged failed at 32 coverages. The rated CBR of the lane was 8.4.

#### Test results

Results of trafficking lane 16 are summarized in table 1. Soil test data are given in table 2. Table 1 contains drawbar pull values for the load vehicle operated over an asphalt strip for comparison with drawbar values recorded on the test lane. The following information was obtained from traffic tests on lane 16.

- a. Roughness. Table 1 shows differential deformations and rut depths at 20 and 32 coverages. Transverse and diagonal differential deformations exceeded rut depth measurements, averaging 3.22 and 3.16 in., respectively, at failure. Rut depths averaged 2.07 in.
- b. Deformation. Average cross-section deformations measured at 20 and 32 coverages are plotted in figure 14. The extra ely rough cross section at 32 coverages reflects the combination

of ridges and ruts developed in the lane. Profile plots in figure 15 show the irregular grade that developed from uneven longitudinal settlement.

- c. Deflection. Average total soil deflections measured at 0, 20, and 32 coverages are plotted in figure 16. Measurements at 0 and 20 coverages were identical and exceeded those at 32 coverages. Elastic soil deflections, shown in table 1, did not change with traffic.
- <u>a</u>. Rolling resistance. Drawbar pull values, shown in table 1, increased steadily with traffic and reached a maximum at 32 coverages.

efficiency of the spot publication of the state of the st

#### SECTION V: PRINCIPAL FINDINGS

From the foregoing discussion, the principal findings relating test load, wheel assembly, tire pressure, and traffic coverages are as follows:

Load, Wheel Assembly, and Tire Pressure	Rated Subgrade CBR*	Coverages at Failure
25,000-lb load; single- wheel assembly; 56x16, 32-ply tire at 100-psi inflation pressure	9.2	70
25,000-lb load; single- wheel assembly; 25.00- 28, 30-ply tire at 100- psi inflation pressure	7.8	200
25,000-lb load; single- wheel assembly; 17.00- 16, 12-ply tire at 100- psi inflation pressure	7.8	100
19,000-1b load; single- wheel assembly; 34x9.9, 14-ply tire at 100-psi in:lation pressure	8.4	32

<sup>\*</sup> All test lanes were unsurfaced.

TABLE 1

SUSCERT OF TRAFFIC DATA, THET ENCTION 7

7 %	- SERVICE	Late 13 failed des	to restring at 70	CONTRAGOS.		Lone 18 railed due	to excensive	farmatal defor-	metions at 200	and an arrange	Lame 15 feiled day	to excessive	ferential dator- mations at 100 coverages	Lane 16 failed due	to rutting at 32		
ograde Daffaction at Approximate Canter Line of Assembly (fs.)	STREET	0.3	4.0	1,10	1	0,2	0.3	1	1	0.4	0.5	4.0	9.0	4.0	4.0	4.0	1
Subgrade Datling at Approximate Caster Line of Assembly (fr.,	TOLOGY	1.0	3.5	2.1	1	1.1	3.0	1	1	1.4	0.0	6.0	7.	1.0	1.0	0.8	1
(Ala)	1	0.8	1.3	3.6	Hegita- gible	0.7	9.6	;	1	0.5	1.5	1.0	9.0	4.4	60	6.5	8.0
7 7	-	6.11	62	61	Segli-	1.3	1.5	1	1	4.1	es es	3.0	4	4.	80	50	1.3
100	1000	3.9	3.0	m ic.	2,6	02	1.0	1	1	3.6	e e	74	0.0	6. 6.	5.1	5.8	ri at
Butteing (fm.)	d	1	1.30	3.33	1	1	0,88	0,88	0	1.16	1	3.30	2.13	1	1.41		1
Battelin (fm.)		1	2,00	4,55	1	1	1.25	1.00	0,88	1.38	}	1.25	2.38	:	2,13		1
(a) (b)	all l	1	1.80	3.69	1	:	3.35	2.13	2.66	3.56	1	1.72	3.83	1		3.16	•
100	ı,	1	2,25	4.50	1	1	1.30	8.9	3.13	4.25	1	8	4,38	1	3.00	4.38	1
1 1 2		1	2,07	3.69	1	1	1,50	99, cu	2,91	3.8	8 0	7.38	3.6	-	2.35	3.22	1
Definition of the last	į	1	8,4	4.7	1	1	1.63	2.3	3,50	87	1	8.8	8.4	1	3.00	4.30	1
1	1	1	0.05	69.0	1	1	0.35	0.30	0.38	0.81	1	P. 22	0.13	3	0.60	1.88	1
383	1	1	0.25	1.00	1	1	0.50	0.75	05'0	7.1		0.47	1.00	8	0.88	2.8	1
light of the same	1		01	*	1	7	-	2.0		-	4	7.00	-0-		-di	-	1
1	I	a	00	20		0	02	100	170	2000	0	8	100	0	8	N	1
14	THE R. P. LEWIS CO., LANSING.	36416,	No life		96e16, 32 pily	25,00:28,	30 pts				17.00-16,	tz pu		34m9.9,	रित मि		3429.9, 14 ply
11	7000	25			10	10					25			19			19
11	ì	27	Ungertheest	A PRINCIPLE	Appeals girth	24	Dispurizable				15	Celebrateraced		316	Unanchood		Asphalt etrip

Notes Single-shoot Landing and 100-pet tive inflation pressure were used in all tests.

TABLE 2
SUMMARY OF CBR, DENSITY, AND WATER CONTENT DATA, TEST SECTION 7

Test Lane No.*	Cover- ages	Depth (in.)	CBR	Water Content	Dry Density (lb/cu ft)	Remarks
13	0	0 6 12 18	6 9 9 6	26.3 25.6 25.1 27.5	94.1 91.6 96.7 94.4	Lane failed due to rutting at 70 coverages
	70	0 6 12 18	7 9 15 11	26.4 23.9 23.8 25.5	95.8 95.5 97.2 94.6	
14	0	0 6 12 18	6 9 9 6	26.3 25.6 25.1 27.5	94.1 91.6 96.7 94.4	Lane failed due to excessive differential deformations at 200 cover- ages
	200	0 6 12 18	6 8 9	26.9 25.8 26.4 26.0	96.5 96.1 95.0 95.6	
15	0	0 6 12 18	7 9 8 8	25.8 23.5 25.7 25.9	93.4 90.0 94.8 92.1	Lane failed due to excessive differential deformations at 100 cover- ages
	100	0 6 12 18	7 9 7	25.8 25.0 27.3 26.7	96.9 99.4 94.1 92.8	
16	0	0 6 12 18	7 9 8 8	25.8 23.5 25.7 25.9	93.4 90.0 94.8 92.1	Lene failed due to rutting at 32 coverages
	32	0 6 12 18	8 10 15** 12	25.3 25.5 24.0 26.1	96.4 96.4 94.7 95.0	

Note: Subgrade material was heavy clay (buckshot; classified as CH) in all lanes.

<sup>\*</sup> All lanes were unsurfaced.

<sup>\*\*</sup> Excessively high value; disregarded in computing rated UBR.




Figure 1. Load vehicle used on lanes 1 and 14



Figure 2. Load vehicle used on lanes 15 and 16




Figure 3. Lame 13 prior to traffic




Figure 4. Lane 13; general view showing transverse straightedge measurement at 70 coverages (failure)




Figure 5. Lane 14 prior to traffic




Figure 6. Lane 14; general view showing transverse straightedge measurement at 200 coverages (failure)




Figure 7. Lane 15 prior to traffic



Figure 8. Lane 15; general view showing transverse straightedge measurement at 100 coverages (failure)




Figure 9. Lane 16 prior to traffic





Figure 10. General view of lane 16 after 32 coverages (failure)





TIRE SIZE	38 X 16
NO. OF PLYS	32
CONTACT AREA, SO M.	242
CONTACT PRESSURE, PSI	103
INFLATION PRESSURE, PSI	100
DEFLECTION, %	29
GROSS ASSEMBLY LOAD, KIPS	25

# 16.24

TIRE SIZE	25.00-28
NO. OF PLYS	30
CONTACT AREA, 30 IN.	227
CONTACT PRESSURE, PSI	110
INFLATION PRESSURE, PSI	100
DEFLECTION, Th	17
GROSS ASSEMBLY LOAD, KIPS	25

#### LANE 13




TIRE SIZE	17.00-16
CONTACT AREA, 35 MI.	201
INPLATION PRESSURE, PAR DEFLECTION, To	100
GREAS ARRESTED LOAD, HIPS	29

#### LANE 15

WOTELENGT SET THE PASS THE SET OF THE SET






TING BIZE	2029.
HO. OF PLYS	14
CONTACT AREA, SO IN.	-164
CONTACT PRESSURE, PM	110
INFLATION PRESSURE, PSI	100
DEFLECTION, %	50
GROSS ASSEMBLY LOAD, KIPS	10

#### LANE 16


TIRE-PRINT DIMENSIONS AND TIRE CHARACTERISTICS TEST SECTION 7 LANES 13,14,15, AND 16


AND THE REAL PROPERTY.




TEST SECTION 7 LANES 13, 14, 15, AND 16

Figure 13







SCHOOL COVERAGES

AVERAGE TOTAL SOIL DEFLECTIONS TEST SECTION 7 LANES 13, 14, 15, AND 18

#### UNCLASSIF IRD

Security Classification

DOCUMENT	CALITRAL	DATA BET
	LUNE KUL	UA 1A - KIN

(Security classification of title, body of abstract and indexing annotation must be enter	tored	subper the	overult i	opert	in all	o atte	(1)
				The second second	Name and Address of the Owner, where the Owner, which is th	CONTRACTOR OF STREET	Annual Property lies
- ORIGINATING ACTIVITY (Competite enthor)	2	REPORT	SECURI	TY C	LARR	FICA	TIO

U. S. Army Engineer Waterways Experiment Station

UNCLASSIF IBD

2. REPORT TITLE

Aircraft Ground-Flotation Investigation Part VIII Data Report on Test Section 7

4. DESCRIPTIVE NOTES (Type of report and inclusive deles) Final Technical Report

S. AUTHOR(S) (Leet name, first name, initial)

6. April 14 martin at martin de la composition d

Sect. 10 Photographic and the action research (NY ALL)

he had been seen to be the state of the bulgarion of the Park and having a control of the second reference of t

with the said and a said of the said of th Right March of the property of the state of

STREET, SECTION OF STREET, STR

wat change and higher and him according to the second of t

Erabston, W. N. Hill, W.J., Jr.

S. REPORT DATE August 1966 74. TOTAL NO. OF PAGES

75 NO. OF BEES

SE CONTRACT OR GRANT NO.

MIPR AS-4-177

A PROJECT NO. 410A

SA. ORIGINATOR'S REPORT NUMBER(S)

AFFDL-TR-66-43, Part VIII.

94. OTHER REPORT NO(9) (Any other numbers that may be level good

None

10 AVAILABILITY/LIMITATION NOTICES This document is subject to special export controls and each transmittal to foreign governments or foreign nationals may be made only with prior approval of the Air Porce Flight Dynamics Laboratory (MDRM) . Wright Patterson AVE. Oblo 45433.

11. SUPPLEMENTARY NOTES

12. SPONSORING MILITARY ACTIVITY

Air Force Flight Dynamics Laboratory Research and Technology Division AF Systems Command Applies Conto

the state of the case of the state of the st

15. ABSTRACT TO THE PROPERTY OF THE PROPERTY OF THE PARTY OF THE PARTY

This data report describes the results of work undertaken as part of an overall program to develop ground-flotation criteria for the C-5A aircraft.

the reference present it was the part being a few and

A STANLEY STANLEY WE HAVE SEEN STANLEY THE REPORT OF THE SERVICE OF SECURIORS the second of a parties where the second

Converse with classification of the second second to the majority of the state of 

#### UNCLASSIFIED

Security Classification

		-1.19	IK A	LIN	IK B	LINKC		
KEY WORDS	ROLK	WT	ROLE	WT	ROLE	WT		
directaft G	round Flotation	Day Colo	TYOU					
Rolling Res				-		2500		
Rear Area /								
	ea Airfields							
	ea Airfields		E E STE			1000	9	
Vehicle Mol	bility					7.74		
ă'			100	0.00		1		
			7 105	FR. 46	1075	E AVUS	01	
					16.57			
				1			100	
	ASSAULT NEWSTRAND					5.5775	15	
The state of the s					- 415 752		0	

#### INSTRUCTIONS

- 1. ORIGINATING ACTIVITY: Enter the name and address of the contractor, subcontractor, grantee, Department of Defense activity or other organization (corporate author) issuing the report.
- 2a. REPORT SECURITY CLASSIFICATION: Enter the overill security classification of the report. Indicate whether "Restricted Data" is included. Marking is to be in accordsace with appropriate security regulations.
- 25. GROUP: Americatic downgrading is specified in DoD Directive 5200.10 and Armed Forces Industrial Manual. Enter the group number. Also, when applicable, show that optional markings have been used for Group 3 and Group 4 as authorized.
- 2. REPORT TITLE: Enter the complete report title in all capital letters. Titles in all cases should be unclassified. If a meaningful title cames he selected without classification, show title classification in all capitals in parenthesis immediately following the title.
- 4. DESCRIPTIVE NOTES: If appropriate, enter the type of report, e.g., interim, progress, summary, annual, or final. Give the inclusive dates when a specific reporting period is devered.
- AUTHOR(3): Exter the manue, of author(4) an above on a in the report. Exter last name, first name, middle initial. If military, show seek end breach of service. The name of the principal author is an absolute minimum requirement.
- 6. REPORT DATE: Enter the date of the report as day, stouth, year, or mouth, year. If more than one date appears on the report, use date of publication.
- 7s. TOTAL NUMBER OF PAGES: The total page count should follow normal regitation procedures, i.e., enter the number of pages containing information.
- 75. NUMBER OF REFERENCER Enter the total number of suferences cited in the report.
- Sa. CONTRACT OR GRANT NUMBER: If appropriate, onter the applicable number of the contract or grant under which the report was written.
- (5, 8s, 6, 8s. PROJECT NUMBER: Easer the appropriate military a artment identification, such as project number, subproject manner, system numbers, task number, etc.
- 9s. OREGINATOR'S TEPORT BUILDINGS: Enter the official repart name by which the decampat will be identified and by the originating activity. This number must be underse to this support.
- OTHER REPORT MUSICALE; If the report has been any any control matters (side of by the originator of the matter).
- the CHARLETY/LINEATION NOTICES: Enter ony lineation of the report, other then those

imposed by security classification, using standard statements such as:

- (1) "Qualitied requesters may obtain copies of this report from DDC."
- (2) "Foreign announcement and dissemination of this report by DDC is not authorized."
- (3) "U. S. Government agencies may obtain copies of this report directly from DDC. Other qualified DDC users shall request through
- (4) "U. S. military agencies may obtain copies of this report directly from DDC. Other qualified usees shall request through
- (5) "All distribution of this report is controlled. Qualified DDC users shall request through

If the reput has been furnished to the Office of Technical Services, Department of Commerce, for sale to the public, indicate this fact and enter the price, if knows

- 11. SUPPLEMENTARY NOTES: Use for additional amplimatory notes.
- 12. SPONSORING MILITARY ACTIVITY: Enter the name of the departmental project office or laboratory sponsoring (paying for) the research and development. Include address.
- 13. ABBTRACT: Enter an abstract giving a brief and factual aummary of the document indicative of the report, even though it may also appear elsewhere in the body of the technical report. If additional apa 'e is required, a continuation sheet shall be attached.

It is highly desirable that the obstract of classified reports be unclassified. Each paragraph of the abstract shall end with an indication of the military security classification of the information in the paragraph, represented as (T3), (S), (C), or (U).

There is no limitation on the length of the statract. However, the suggested length is from 150 to 225 works.

16. KEY WORDS: May words are technically meaningful terms or short threes that characterize a report end may be used as latex sarries for cataloging the report. Key words must be selected so that no security classification is required. Identifiers, such as equipment model designation, tade mane, military project code name, grogwestic location, may be used as key words but will be followed by an indication of technical context. The assignment of links, rules, and weights is operable.

UNCLASSIFIED